Site Order Book

Restoration Improvements of Mahalakshmi layout, Balaji layout, Best Country-II & III, Bhaskar Reddy, Andhra layout, Tirumalanagara and surrounding areas in ward no-03 of Yelhanka New town Sub division (PAKAGE NO-10)

25/11/2021

* Atturu Lake Road Excavation
* Duo marvel Layut 2nd cross Road Earth work Excavation

AE

26/11/2021

* Atturu Lake Road Excavation
Duo marvel Layut 2nd cross Road Excavation

AE

28/11/2021

* Atturu Lake Road PCC work
Do Proper mixing As per proportion
* Duo marvel Layut PCC work at 2nd cross Road
* 4th cross Road Excavation

AE

29/11/2021

* Atturu Lake Road PCC work
* 4th cross Road Excavation.
Mahalakshmi Layut Excavation work

AE

30/11/2021

Best County-2 2nd cross Road Excavation

Best County-3 1st cross Rad Ganpathi Temp Road Excavation

Duo marwal Layut 2nd cross Road Excavation

Muneshwar Layut main Earthwork

Attur Lake Rad Pcc work

4th cross Road Pcc work

mahalakmi layut Earth work Excavation

AE.

1/12/2021

Attur Lake Road Steel work

Duo marwal Layut Steel work

muneshwar Layut main Road Pcc

Raft concrete Attur Lake Road

2nd cross Road

mahalakshi Layut Pcc work

AE

02/12/2021

Bar Bending work At Attur Lake Road

Bar Bending work At 4th Cross Road & mahalakshmi Layut

Best Court-2 Earth work Excavation

Raft concrete at Attur Lake Road

Bar Bending work at 3rd cross Road & muneshwar Layut

AE

03/12/2021

Earth work Excavation in Andra Layout
4th cross Road, 3rd cross Road
Duomarvel Layout 2nd cross Road Raft concrete
Atturu Lake Road Raft Concrete
maneshwara Layout Raft Concrete work
mahalakshmi layout Bottom Concrete
Atturu Lake Road work Shuttering work
Kerb Betty work at maheshwara Layout
water tank Road

AE.

04/12/2021

Shuttering work at maneshwara Layout main Road
Raft Concrete at Atturu Lake Road
maneshwara Layout 11th main Road Earth work
Centering work at mahalakshmi Layout
Kerb Painting at mahalakshmi Layout
Earth work Excavation in Andra Layout
Best county - 2 Bar Bend work
work concrete at Duomarvel Layout

AE.

06/12/2021

Decentiy work at Atturu Lake Road

Kerb Painty at mahalakshmi Layout

Earth work Excavation maruthuru layout

Shuttring work at Atturu Lake Road

Best county - 2 road shutting work

Earth work in Andra Layout

Do curing work over

4th cross Road Rcft concrete

A.E Sir visit maruthuru Layout main Road

AE.

07/12/2021

Do Curing

Best county 3 Road Excavation

Earth work Andra Layout

Atturu Lake Road Backfilling work

PCC work at maruthuru layout

AE.

08/12/2021

Do Curing work at Duo marvel layout

maruthuru layout Earth work

Earth work at Atturu Lake Road

Best county - 3 Road Excavation

AE.

09/12/2021

maneshwara Layout Bar Bending work

Best County - 2 No work

Best count - 3 GSB formation

Andrag Layout AE & AEE sir visiting

Site check PCC work

Ramu/AE

10/12/2021

maneshwara Layout wall Concrete work

Attur Lake Road AE sir & AEE sir visit

Besty Count Rolling work

Attuar Lake wall Concrete

Best county - 3 3rd main Road Earth work

Excavation

maneshwara Layout 11th main 1st cross Road

Bottom Raft Concrete

manghwan Layou PCC work

Ramu/AE

11/12/2021

maneshwara layout wall Concrete work

Attura Lake Road steel work

Curing work

Duo marvell Layut wall Concrete

Attura Lake Road wall Concrete

Ramu/AE.

Atturu Lake Road cc work concrete

cc work Concrete Duo marvel

Back filling work at Duo marvel

wet mix Beat cavity - 3

AE.

14/12/2021

EE sir & AE, AEE sir visit muneshwara layout

cc work concrete work, Atturu Lake Road

muneshwara Layout 12th main Road 1st cr

Bar Bending work

Duo marvel 1st cc work concrete

mahalakshmi layout cc work Concrete

Earth work Excavation in Atturu Lake Road

Back filling work at Atturu Lake

AE.

15/12/2021

Do Curing Atturu lake Road

Raft Concrete at muneshwara Layout

~~Kerb laying work~~

Chca Drain Bed level &

Earth work for Duomarvel Layout

Dismantled culvert Dcch Slab

Atturu Lake wall concrete

AE sir visit Duomarvel Layout

Slab Laying work in Duomarvel

AE.

16/12/2021

Bar Bending work at Atturu lake Road

Duomarvel 1st cross Road Raft concrete

Shuttering work at muneshwara Layout

AE.

17/12/2021

Andra Layout Pce work

Atturu lake cover slab cast in site

muneshwara Layout Kerb Laying work

Curing work at muneshwara

wall concrete Duomarvel

AE.

18/12/2021

Maruthinagar layout kerb laying work
AE & AEE site visit Attur lake Road

Mahalakshmi layout Cover slab laying

AE

20/12/2021

Raft concrete attur lake Road
Mahalakshmi Layout slab laying work
curing work at attur lake

AE

27/12/2021

Earth work Excavation attur lake Road
Best coney-2 slab laying work
wall curing at Attur Lake Road
wall concrete Andra layout 2nd cross
Road

AE

28/12/2022

Atturu lake PCC work
mahalakshi layout kerb work
mahalaxmi layout cc road concrete at
3rd main Road

AE

29/12/2022

Road Earth work in mahalaxmi layout
cc road Concrete muneshwar layout

AE.

31/12/2021

Earth work in mahalaxmi Layout
Drain work concrete muneshwar layout

AE.

1/01/2022

Atturu lake Drain work concrete
Andra Layout Drain work concrete

AE.

18/01/2022

Scarifying work at Mahalakshmi Layout

AE

19/01/2022

Do curing

Slab laying work at Atturu lake Road

AE

24/01/2022

Kerb lining work & Pointing work at 3rd main 2nd cross Road

curing work at Atturu lake Road

AE

04/02/2022

cumm layig work mahalakshmi Layout

Single drum vibrator Rollig

Do Proper Rollig

EE



05/02/2022

Rollig work at mahalakshmi Layout

EE



07/02/2022

wet mix Spreadig work at 1st main mahalakshmi Layout

main Road cumm layig work

EE



09/02/2022

cumm Rolig work mahalakshmi Layout

water Sprinklig for cumm

Do Rollig Propevly

EE



02/03/2022

BBMP Commissiony sir visit mahalakshmi layut under service Road.

BAE

26/03/2022

Road Earthwork and formation work in Andra Layut

Base court → formating work

BAE

27/03/2022

Storm layiy work in Andra layut

Roliy work

BAE

08/04/2023

Asphalt work at mahalakshi layut DBM & BC work 3rd main - 1st cross Road

3rd main DBM & BC Layiy

Do Proper Roliy

BAE

16/05/2022

~~Veer~~ Veer Sagar main Rod Culvert Excavation

Road formation veer Sagar main Rod

AE.

17/05/2022

3rd cross Road veer Sagar wall Concrete work

main Road Pcc work

AE

18/05/2022

main Road steel work

Road formation work

AE

20/05/2022

3rd cross Rod shuttering work

Earth work in 3rd cross Rod

AE

25/05/2022

Cc all concrete 3rd cross Road

Slab laying work veersagar main



26/05/2022

veersagar main Road formation work



27/05/2022

veersagar main Road formation work



01/06/2022

GS B laying work in veersagar main Road



02/06/2022

GSB laying work in veersagar main footpath work at Bhel Layout

03/06/2022

Roling work at veersagar main Road Bhel footpath work

AE

04/06/2022

Kerb laying work at veersagar main Road footpath Tile work

AE

08/06/2022

Concrete laying work at veersagar main Road
Kerb laying work at veersagar main Road
Excavation work for CC Road

AE

09/06/2022

Roling work at veersagar main Road

AE

11/06/2022

PCC work at veer Sagar near Road

Comm laying work at veersagar main Road

AE.

12/06/2022

Concrete work for cc Road
Compaction work for comm

AE.

14/06/2022

PCC work for cc Road
Compaction work for comm

AE

22/06/2022

Concrete work for cc Road

AE

26/06/2022

DBM work for veer sagar main Rail

Do Proper Ballast

Extraction



27/06/2022

DBM work for veersagar main Rail

Thiruvalangadu Nagar area work

Extraction



29/06/2022

DBM work for veersagar area Rail

Thiruvalangadu Nagar Compaction and

Extraction work



01/07/2022

DBM for veer sagar main Rail

Extraction



02/07/2022

BC work for veer Sagar main Rd

DBM work from Thirumalanagar Extraction work



04/07/2022

BC work for veer Sagar main Rd
~~250~~ 20 lads
Extraction



05/07/2022

DBM work for veer Sagar main Rd
DBM work for Thirumalanagar
BC work veer Sagar main Rd
Extraction



06/07/2022

BC work for Thirumalanagar main Rd

DBM for cross Road
Extraction



7/07/2022

BC work in Thirumala nagar
10 loads
Extraction



8/07/2022

BC work Thirumala nagar
8 loads
Extraction



09/07/2022

BC work Thirumalanagar
5 load
Extraction